

# Recommendation

For Flooring Manufacturer



## ErgoFloorAps

Viborgvej 9  
DK-7160 Tørring

Email: [ergofloor@ergofloor.dk](mailto:ergofloor@ergofloor.dk)

Product Name	Recoating	First Care after Recoating	Cleaning	Intensive Cleaning After Recoating
ErgoFloor BlackLine	LOBADUR® 2K Ultra 2.0 or LOBADUR® 2K Supra A.T. According to technical Information	LOBA® FloorCare matt LOBA® FloorCare LOBA® ParkettCare According to technical Information	LOBA® Cleaner	LOBA® CareRemover

Technical Information of all mentioned products are part of this recommendation as well as general care and cleaning instructions for this kind of floor. Information and Instructions are available at [www.loba.de](http://www.loba.de)

- LOBADUR® 2K Ultra 2.0
- LOBADUR® 2K Supra A.T.
- LOBA® Cleaner
- LOBA® FloorCare
- LOBA® FloorCare matt
- LOBA® ParkettCare
- LOBA® CareRemover

Mentioned Products were tested from the LOBA Technical Department 09.02.2011

